



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 29, 2010

Reviewed: PBB

Mine Name: Beaver Shaft	Permit Number: M037/0026
Operator Name: Denison	Inspection Date: April 15, 2010
Inspector(s): T Munson	Time: 3-4 PM
Other Participants: none	Mine Status: active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts) drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$348,686

Fees: fees current

Purpose of Inspection: Routine Visit.

Inspection Summary:

I drove through the site and although the hoist was running no one was on the site. There was a considerable amount of culvert stockpiled on site and some drilling equipment was evident.

Conclusions and Recommendations:

The Division will continue to do routine inspections when in the area.

Inspector's Signature [Signature]

TM:vs

cc: marie_mcgann@blm.gov

cwoodward@denisonmines.com

O:\M037-SanJuan\M0370026-LaSalSnowballMines\Inspections\Beaver Shaft inspections\insp04152010.doc